COMMONWEALTH OF KENTUCKY BEFORE THE PUBLIC SERVICE COMMISSION

In the Matter of:

GRAYSON RURAL ELECTRIC COOPERATIVE CORPORATION		CASE NO. 98-590
)	CASE NO. 96-590
ALLEGED VIOLATION OF COMMISSION)	
REGULATION 807 KAR 5:041)	

ORDER

Grayson Rural Electric Cooperative Corporation ("Grayson RECC") is a Kentucky corporation that engages in the distribution of electricity to the public, for compensation, for lights, heat, power, and other uses. Grayson RECC was formed under KRS 279.010 to 279.220, and is a utility subject to Commission jurisdiction pursuant to KRS 278.010 and KRS 279.210.

KRS 278.280(2) directs the Commission to prescribe rules and regulations for the performance of services by utilities. Pursuant to this statutory directive, the Commission promulgated 807 KAR 5:041, Section 3(1), which requires electric utilities to maintain their plant and facilities in accordance with the standards of the National Electrical Safety Code (1990 Edition) ("NESC"). The Commission also promulgated 807 KAR 5:006, Section 24, which requires a utility to adopt and execute a safety program.

Commission Staff has submitted to the Commission a Utility Accident Investigation Report dated September 29, 1998, appended hereto, which alleges:

- 1. On February 7, 1998, Harry Hosack, Jr., suffered burn injuries to his left hand and left foot while connecting a jumper to a 7200-volt primary line in Carter County, Kentucky.
- 2. At the time of the incident, Grayson RECC owned and operated the facilities in question.
 - 3. At the time of the incident, no protective covering was being used.
 - 4. At the time of the incident, Eugene Bush was in charge of the work site.
- 5. At the time of the incident, Eugene Bush was an employee of Grayson RECC and Harry Hosack was an employee of EZ Electric, Inc. and both were acting within the scope of their employment.
- 6. At the time of incident, EZ Electric, Inc. was acting within the scope of a contract with Grayson RECC to construct and install certain utility plant.
- 7. NESC Rule 420H requires a person to use the personal protective equipment and protective devices, and the special tools provided for the work.
- 8. NESC Rule 443A1 requires that a person working on energized lines and equipment must be insulated from energized parts, or must be isolated or insulated from ground and grounded structures and potentials other than the one on which he is working.
 - 9. Hosack failed to comply with NESC Rules 420H and 443A1.
- 10. Bush failed to require that all safety rules and operating procedures were observed by those under his direction. His failure to do so is a violation of NESC Rule 421A, which requires a person in charge to adopt such precautions as are within his

authority to prevent accidents and to see that the all safety rules and operating procedures are observed by those under his direction.

Based on its review of the Utility Accident Investigation Report, and being otherwise sufficiently advised, the Commission finds that *prima facie* evidence exists that Grayson RECC failed to comply with Administrative Regulation 807 KAR 5:041, Section 3, and 807 KAR 5:006, Section 24.

The Commission, on its own motion, HEREBY ORDERS that:

- Grayson RECC shall submit to the Commission within 15 days of the date of this Order a written response to the allegations contained in the Utility Accident Investigation Report.
- 2. The Utility Accident Investigation Report of September 29, 1998, a copy of which is appended hereto, is made part of the record of this proceeding.
- 3. An informal conference with Commission Staff is set for December 11, 1998, at 10:30 a.m., Eastern Standard Time, at the Commission office at 730 Schenkel Lane, Frankfort, Kentucky, in Conference Room 2, to consider any matter that would aid in the handling or disposition of this proceeding. Grayson RECC shall be represented by an officer with authority to represent the utility.
- 4. The Commission will consider a date for a Show Cause Hearing, pending the disposition of this case, if any, at the informal conference.

Done at Frankfort, Kentucky, this 24th day of November, 1998.

PUBLIC SERVICE COMMISSION

Chairman

Vice Chairman

Commissioner

ATTEST:

Executive Director

UTILITY ACCIDENT INVESTIGATION REPORT

Utility:	Grayson Rural Electric Cooperative Corporation						
Reported By:	Carol Hall Fraley – President and CEO						
Dates & Times							
Accident Occurred:	02/07/98 — Approximately 12:20 p.m.						
Utility Notified:	02/07/98 – Approximately 1:45 p.m.						
PSC Notified:	02/07/98 - Approximately 3:3	8 p.m.		·			
Investigated:	02/10/98						
Written Report Rcvd:	02/12/98						
Location of Accident:	Iron Hill, on Route 7 in Carter County, Kentucky						
Description of Accident:	Mr. Hosack was connecting a jumper to a 7200 Volt primary line. Mr. Hosack made contact with the energized line and was shocked and burned. Mr. Hosack was not wearing rubber gloves.						
Victims:				y		<u>,</u>	
Name:	Harry Hosack, Jr.		Fatal:	No	Age:	33	
Addr./Empl.:	EZ Electric, Inc., 4812 W. Pea Ridge Road, Huntington, West Virginia 25707						
Injuries:	Entry wounds, left hand, index and middle finger, blister in palm of hand, flash burns on the knuckles and there is an exit wound in the top of the left foot. Also, there are abrasions on the left hip and lower leg.						
Witnesses:	Name		Address/Employment				
	Tony McGlone		EZ Electric, Inc.				
	Mike Miller		EZ Electric, Inc.				
	Name		Address/Employment				
	Gene Bush		Grayson RECC				
Sources of Information:	Tony McGlone		EZ Elect	ric, Inc.			
accident Investigation Report						Page	

September 29, 1998

September 27, 1770					•		
	Mike Miller		EZ Electric, Inc.				
Probable Violations:	There was a probable violation of 807 KAR 5:041, Electric, Section 3(1) and						
Trobable violations.	NESC, Section 42	2, Subsection, 420h	H. Tools and Protec	tive Equip	ment		
		Minimum	Applicable NESC				
Line Clearances At		Allowed by	Edition ¹		Constr.		
Point of Accident:	Measured	NESC	1990	Volt.	Date		
Primary:	35' — 10"	18' – 6"	Table 232-1	7200	1941		
Neutral:	31' – 11"	15' – 6"	Table 232-1	N/A			
Telephone:	25' – 2"	15' – 6"	Table 232-1	N/A			
Telephone:	24' – 0"	15' – 6"	Table 232-1	N/A			
Date of							
Measurement:	02/10/98						
Approximate Temp.:	40°F						
Measurements Made			•	,			
By:	Gene Bush, Kim Bush, Grayson RECC employees and Bob Ueltschi, PSC						
Investigated By:	Bob Ueltschi						
Signed:	Ros C						

Attachments A. Grayson RECC's Accident Report

B. Photographs of Accident Site

Current edition adopted by the Commission. If clearances are not in compliance with the current edition, then the edition in effect when the facilities were last constructed or modified would apply.



Attachment A
Grayson RECC's Accident Report

FEDERATED RURAL ELECTRIC INSURANCE CORPORATION P O. Box 15147 Strawnee Mission, KS 66215 (913) 541-0150

INVESTIGATION REPORT

PUBLIC ACCIDENT

ELECTRICAL CONTACT

INSTRUCTIONS:

- 1. Forward original to Federated
- 2. Attach diagram & photographs
- 3. Use additional sheets of paper if necessary

COOPERATIVE:	Name Grayson Run Address 109 Bagh			orporation	Telephone No	.606-474 - 5136
	TO Dago	· raik, Glayso	on, KI 41143			
DATE OF ACCIDENT:	2 / 7 / 98	AM PM	Cooperative Notified	2 / 7 / 9	8 1:30	AM PM
LOCATION:	Iron Hill, Rou	ite 7, Carter (County			
DESCRIPTION OF ACCIDENT:	Mr. Hosack was	connecting a j energized lin	umper on an	A6, double	dead-end and	made
	Name		Address		Telephone No.	Occupation
CLAIMANTS:	1. Harry Hosack, 2. 3. 4.				3659 : Jo on, W VA 2570	urneyman Line 7
EXTENT OF INJURY:	1. Burns on palm 2. Burn on top o 3. Left lower le 4. Left side bru Ambulance, Doctor, Hospi	f left foot g skinned ised				
TREATMENT:	Admitted to Ki Released about				ning.	
COOPERATIVE EMPLOYEES AT SCENE:	Name Eugene Bush was working abou		Job Title astruction S away but was		scene.	
VITNESSES:	Name Tony McGlone Mike Miller		Address tric, Inc.		Telephone No 04-736-8659 04-736-8659	
AW OR OTHER OFFICIALS OVESTIGATING:	Mr. Robert Uelts	schi, Kentucky	Public Serv	ice Commissi	on	

WEATHER AND TERRAIN CONDITIONS:	40 - 45° and Sunny, ground very wet Pole was located on a hillside.							
SYSTEM PROFILE:	7200 t	olts sin		le structuresetc. , double dea er	ad-end with	tap, cutout	, guy wire,	_
PROTECTIVE DEVICES:	Type N/A	L	ocation		Rating	Did	They Operate?	
DID OUTAGE OCCUR?	Yes No Power	Date Was on u	/ / p to that	Time	AM PM	Duratio	n	
WAS COOPERATIVE NOTIFIED OR AWARE OF WORK IN THE AREA? EXPLAIN:	Cooper	ative ha	d experie	•		" of snowfall signed.	L. Contract	
CLEARANCES:	of the accide	int, measurem	ent and photogra	aphs are needed bef	ore returning to c	riginal condition. Do	arances are reduced becoment what caused these to point of impact.	a usi
CODE REQUIREMEN	TS							
FOR LINE IN		ce excee	ded NESC r	requirements	- accordi	ng to Mr. Uel	tschi.	
DUESTION:								<u> </u>
AGENCY NVOLVED:	-:	ner, crane, cons	struction equipn	nent, etc. Give mea	surements, make,	model, or serial num	ber. Describe any warn	ing
DDITIONAL OMMENTS:	Photos	of the a	accident s	ite are att	ached.			
·				·				_
EPARED BY:	Garature Signature	oppel	Oury	Preside	ent & CEO	2 /11 /98 Date	1606 1474 5136 Telephone No.	_

6 cwc conductor Telephone Fguiphent. THANS. 7 Double Deaderde 7200 VOIT

Attachment B Photographs of Accident Site







